Overview

An important part of your experience in woodworking will be learning to follow practices and procedures that will prevent injuries to YOURSELF and OTHERS.

Develop a good attitude toward safety. This means that you have a strong feeling toward the importance of safety and are willing to give time and attention to learning the safest way to perform your work. It means that you will be certain to work carefully and follow the rules even when no one is watching you.

Carefully study the safety rules which follow. Your instructor may also recommend some additional rules. If you follow the rules and directions carefully*s carorl p toblsoty(mayhab (to(d)-2 (l5gfe)n 3 (or)-3 (f 84>h

to p hoblselp.ER7.3-3 ( )-4.733 ( )]TJ EMC_ET /17 <</MCID 6 >>BDC_EMC_BT /18 <</MC

The types and limitations of any personal protective equipment (PPE) that is required to be used in the shop.

Limitations of the particular equipment.

Procedures to be followed in the event of a machine malfunction or damage to the equipment.

Procedures to be followed in the event of an emergency (i.e. injury).

Equipment and general shop maintenance and cleaning procedures.

Use of approved materials on tools. Never use reclaimed lumber or materials with metal hardware on tools.

All training must be documented in writing with the records maintained by the shop supervisor.

General Safety Rules

Work procedures and shop practices described are effective methods of performing given operations. Use special tools and equipment as recommended. Carefully follow all safety warnings and cautions. Note that these warnings are not exhaustive. Proceed with care and under proper supervision to minimize the risk of personal injury or injury to others. Never use any tools or machinery without first receiving training.

Most power tool accidents can be avoided. Roughly 80% of accidents are caused by workers without the right safety attitude. Never work alone. At least two people must be present when power tools are in use. No horseplay is allowed. Never work while impaired. These workers do not take safety seriously. Instead of being safe, they put everyone in danger.

BENCH ORGANIZATION

CONSIDERATION OF OTHERS

FIRE PROTECTION

Re-familiarize yourself with the location of all fire alarms and fire extinguishers.

Many finishing materials, thinners, etc. are highly flammable. Others are toxic. Because of this, it is important that these materials be used only in approved areas. Prior to use, make sure you are in a project space that allows application of such materials.

Close cans of finishing materials and thinners immediately after use.

Use flammable liquids in very small quantities. Be sure the container is labeled.

Consult workers near you to determine whether any potential crossover hazards might be present.

Dispose of oily rags and other combustible materials immediately, or store them in an approved container.

FLOOR SAFETY

The floor should be clear of scrap blocks and excessive litter/clutter. Keep projects, sawhorses, and other equipment and materials you are using out of traffic lanes. Immediately wipe up any liquids spilled on the floor. Periodically sweep up sawdust as you work to prevent slippery conditions on floors. Floor areas must be kept free of debris and other hazards that may result in slips, trips or falls.

HAIR & CLOTHING

Dress properly for your work. Remove coats and jackets. Secure or remove loose clothing that can potentially get caught in power tools or other shop appliances. It is advisable to wear a shop apron that is snugly tied. Wear close toe shoes. Keep long, loose hair restrained and securely tied back to prevent machine and tool entanglement.

STANCE

Stand in a comfortable, balanced position when working with power tools. Both feet should be firmly on the floor. Try to be as relaxed as comfortable: if you are unsure about your comfort with the equipment, consult a supervisor.

SUPERVISOR ON DUTY

WATER

Never work in or around water with power tools. Water increases the chances of severe electrical shock.

WOOD

Defects in the wood can be dangerous. Check the stock carefully for knots, splits, and other defects.

WORKING SPEED

Do not “rush and tear” through your work. The good crafter knows that a steady, unhurried pace is safest and produces the best work. Allow for machinery to come to full speed before engaging any materials with the tool. Never start a piece of machinery with materials engaged.

Power Equipment Safety Rules

Modern power woodworking machines can save large amounts of time. Learning how to use them safely will be-2 (.)-3 (tgAl)011E0003018iCeT2

If you hear a clicking noise, turn off the machine at once. This indicates a crack in the blade. If the blade breaks, shut off the power and move away from the machine until it stops.

Turn off the machine as soon as you have finished your work. If the machine has a brake, apply it smoothly. Do not leave the machine until it has stopped running.

Safety Rules for Drill Presses

Check the speed setting to see that it is correct for your work. Holes over ½ in. should be bored at the lowest speed.

Use only an approved type of bit. Bits with feed screws or those with excessive length should not be used.

Mount the bit securely to the full depth of the chuck and in the center.

Remove the key immediately.

Position the table and adjust the feed stroke so there is no chance of the bit hitting the table.

The work should be placed on a wood pad when the holes are drilled all the way through.

Work that will be held by hand should be center punched.

Small or irregular shaped pieces must be clamped to the table or held in some special fixture.

Feed the bit smoothly into the work. When the hold is deep, withdraw it frequently to clear the shavings and cool the bit.

When using special clamping setups or a hold saw or fly cutter, have your instructor inspect it before turning it on.

Always have your instructor check setups for routing and shaping.

SafetyRulesfor Finishing

Wear safety glasses when applying finishing materials.

Wear rubber gloves, goggles, and rubber apron when applying bleaches and acids.

Thinners and reducers such as naphtha, benzene, lacquer, thinner, and enamel reducer should be applied in a well-ventilated room. Fumes have a toxic effect.

Store all chemicals and soiled rags in proper safe containers. Many chemicals and rags are highly flammable.

Spraying should be performed in a well-ventilated booth or outside to reduce toxic fumes.

Do not smoke while sanding or applying a finish. Not only does dust or vapor mixed with smoke create a hazard to your health, but it may start a fire.

Wash your hands well after applying a finish in order to remove any toxic materials that you have handled.

Know where the sink, shower, or eye wash station is located in the event you are burned by a finishing material.

Provide an approved fire extinguisher in the finishing area.

SafetyRulesfor Jig Saws

Be certain the blade is properly installed. It should be in a vertical position with the teeth pointing down.

Roll the machine over by hand to see if there is clearance for the blade, and if the tension sleeve has been properly set.

Make multiple angled cuts to achieve a cut with a tight radius.

Check the belt guard to see that it is closed and tight.

Keep the hold-down adjusted so the work will not be raised off the table.

When the saw is running, do not permit your fingers to get directly in line with the blade. The work can usually be held on either side of the cutting line.

SafetyRulesfor Jointer

Be sure you have the instructor's approval to operate the machine.

Before turning on the machine, make adjustments for depth of cut and position of fence.

Do not adjust out-feed tables or remove guard without the instructor's approval.

The maximum cut for jointing an edge is 1/8 in.; for a flat surface, 1/16 in.

Stock must be at least 3/8 in. thick, unless a special feather board is used.

Feed thework so the knives will cut "with the grain." Use only new stock that is free of knots, splits, and checks.

Keep your hands away from the cutter-head even though the guard is in position. Mainta re Wsw-4 <010>3 1yan xh yous-3 (gh)blo(thi)

NEVER leave the laser running unattended. There should always be a person in the room watching the laser cutter while it is running. NO EXCEPTIONS!

Never run the laser cutter without all the proper ventilation equipment.

Do not continue a cut if it is creating large flames. Fire is a huge risk to the laser and its ventilation system. Stop your cut immediately and switch to a lower power setting.

Know how to stop the machine and what to do in the case of a fire.

To turn off the laser, simply open the lid of the laser cutter. If you want to keep the lid closed, you can press and hold the pause button.

If there is a fire:

- Open lid to stop the laser.
- Put an acrylic sheet over the burning material to smother the fire (always keep a sheet of acrylic handy when cutting for this reason).
- If you can reach it, push up the blast gate to stop air flow.
- Use the fire extinguisher (it is located in 1203 on the left side of the studio door)
- If you cannot put out the fire or feel that you are in danger, call the campus Security

Check to make sure that the material you are using is in the allowed list of materials. If you aren't sure, DON'T CUT IT. Ask for help. Never cut PVC or chlorinated plastic. You should always know what material you are cutting, and chlorinated plastics should be avoided because they release chlorine gas when cut.

Do not try to cut metal in the laser cutter.

During the cut, stand to one side of the cutting line.

Large saws will have two handles. Keep both hands on them during the cutting operation. Small saws should also be guided with both hands when possible.

Always unplug the machine to change blades or make major adjustments.

Always use a sharp blade with plenty of set.

SafetyRulesfor Portable Electric Drills

Disconnect the power before changing router bits.

Safety Rules for Sanding Machines

Be certain the belt or disc is correctly mounted. The belt must track in the center of the drums and platen. Do not operate the disc sander if the abrasive paper is loose.

Check the guards and table adjustments to see that they are in the correct position and locked securely in place.

Use the table, fence, and other guides to control the position of the work, whenever possible.

Never sand without a table supporting the stock.

Small or irregular-shaped pieces should be held in a hand clamp,

Use the correct blade for the stock (thickness) and curve (sharpness) being cut.

Never try to turn a small radius with a wide blade. The radius should not be more than three times the blade width.

Clamp the blade securely in both chucks with the teeth pointing down.

Adjust the guides so they properly support the blade.

Adjust the hold down so that it applies light pressure to the stock.

Rotate the motor by hand to check that all adjustments have been made properly.

Plan cuts to avoid backing out of curves.

Do not force the work into the blade. This can cause the blade to bend the break.

Keep your fingers out of line with the saw.

SafetyRulesfor Shaper

Whenever possible, install the cutter so the bottom of the stock is shaped.

In this way the stock will cover most of the cutter and act as a guard.

Make sure the cutter is locked securely to the spindle.

Always position the left fence so that it will support the work that has passed the cutters.

Adjust the spindle for correct height and then lock in position.

Rotate the spindle by hand to make sure it clears all guards, fences, etc.

Check the direction of rotation by snapping the switch on and off; watch as the cutters come to rest. ALWAYS FEED AGAINST

Use one hand to push the saw through the stock. Use the other hand to hold the stock against the fence. Keep both hands away from the cutting line.

Cut only one piece of wood at a time.

Feed the blade slowly.

Safety Rules for Surface (in)-4 (g)7 (.)]TJ EM83BT /P 5 >2MCID 9 >>BDC /C2_

Know and follow the general safety rules for operating power tools.

Remove all loose knots from the stock before surfacing.

Do not surface stock shorter than the distance between the centers of the in-feed and out-feed rolls. This is usually about 12 inches (300 mm), or more.

Never stand directly behind a board being surfaced. The stock could kick back and cause an injury.

The saw is equipped with a guard and a splitter. Be sure to use them.

Set the blade so it extends about ¼ in. above the stock to be cut.

Stand to one side of the operating blade and do not reach across it.

Let the blade get to full speed before cutting.

Never reach under the table to tighten locks, remove scrap or make adjustments while the saw is running.

Never reach over or across the blade while the saw is running, even with the upper guard in place.

Maintain a 4 in. margin of safety. E.g. clamp a small piece of stock to a larger piece to cut safely.

Stock should be surfaced, with at least one (e)4c4ast oce joitl oce ntti a c